

Victa and A.E.S.L. Airtourer Series Aeroplanes

---

**AD/VAT/20**

**Centre Flap Spar - Inspection**

**6/64**

- Applicability: Victa Airtourer 100 and 115 not incorporating Victa Mod. B141 and which have exceeded 500 hours time in service.
- Requirement: Inspect the centre flap spar in the region of the actuating bracket P/N 16105/1 for cracking. If cracking is found repair in accordance with an approved scheme before further flight.
- Compliance: At intervals not exceeding 100 hours time in service, after 1 September 1971.