

Victa and A.E.S.L. Airtourer Series Aeroplanes

---

**AD/VAT/27      Crankcase Breather Aerobatic Oil Trap - Removal      11/66**

Applicability:    Victa Airtourer 100 fitted with Mod. No. B199.

Document:        Victa SB No. 63.

Compliance:     Within 50 hours time in service, after 6 December 1966.