

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/31 **Control Torque Tube Assembly - Inspection** **9/79**
Amdt 1

Applicability: Airtourer 100 and 115.

Requirement: Inspect both upper and lower cut outs in the Control Column Torque Tube P/N 52131/30 for cracking. The area can be inspected by removing the arm rest front panel P/N 53018/1.

Compliance: At intervals not exceeding 100 hours time in service after 30 September 1979.