AD/PMC/21 Three Blade Propeller Hub - Modification or Replacement 7/71

Applicability: Models D3A32C77, C79, C88 and C90 models with no model number change letter or letter “A” to “J” fitted to Cessna 206 series aircraft with normally aspirated Continental IO-520 engine not modified in accordance with McCauley SB No. 88 (AD/PMC/20 refers).

Document:

1. Cessna SL SE71-15; or
2. McCauley SB No. 89.

Compliance:

1. For propellers which have completed 600 hours or more total time in service - within 25 hours time in service after 30 July 1971.
2. For propellers which have completed 500 hours total time in service - before achieving 600 hours total time in service.