AD/HU 369/21 Stabiliser Strut Damper Plunger - Inspection and Replacement 12/76

Applicability: All models fitted with P/N 369A2001-601 shock mounted stabiliser strut assembly.

Document: 1. Hughes SIN HN-102.1; or

2. FAA AD 76-19-03.

Compliance: For Part 1 - Within 25 hours time in service after 25 Nov. 1976.

For Part 2 (if required) - Within 100 hours time in service after 25 Nov. 1976.