AD/X-TS/3 Canard Rear Spar Reinforcement 2/2000 TX

Applicability: Models X-TS 150 and 150B serial numbers 001 to 003 and 005 to 030 inclusive.

Requirement: Modify the canard rear spar bracket in accordance with Eagle Service Bulletin 1074.

Compliance: Within 100 hours time in service after the effective date of this directive.

This Airworthiness Directive becomes effective on 24 December 1999.

Background: This Directive is issued to provide additional strength to the canard rear spar bracket, to enable the aircraft to meet certification requirements.