AD/BAe 146/38 Generator Control Unit (GCU) Replacement 1/92 TX

Applicability: As specified in the requirement document.

Requirement: Action in accordance with BAe 146 Mandatory Alert Service Bulletin 24-A97.

Compliance: Prior to 17 November 1991.

Background: BAe have advised that failure of affected GCUs to detect a single phase feeder line open circuit may lead to inaccurate instrument readings.