AD/BEECH 36/14 Wing Front Spar 2/99 Amdt 1

Requirement: CANCELLED.

Background: Beechcraft Service Instruction 0514-035 Rev II has been superseded by Service Bulletin 2538 Rev I with reduced model applicability. Corrosion inspection of the upper and lower wing spar caps is called up in the aircraft's maintenance program - therefore separate AD action is no longer considered necessary.