AD/BEECH 36/32 Seat Recline Actuators 12/87

Applicability: All models with S/Nos listed in the Requirement document which are equipped with Hydrolock seat recline actuators on copilot, 3rd and 4th seats.

Requirement: Action in accordance with Beechcraft SB No 2175 R1.

Note: FAA AD 87-18-06 refers.

Compliance: Within 100 hrs time in service after 3 December 1987 or at the next scheduled inspection for Maintenance Release issue, whichever is later.

Background: The manufacturer reports instances of inadvertent actuation of the seat mechanism which in some phases of flight operation could be a hazard.