AD/BELL 212/18 Tail Rotor Pitch Horns - Inspection 10/77

Applicability: All models fitted with pitch change horns P/N 212-010-716-5 or -9.

Document:
1. Bell SB No. 212-77-7; or
2. FAA AD 77-17-03.

Compliance: Within 25 hours time in service after 15 September 1977 and thereafter at intervals not to exceed 100 hours.