AD/BELL 212/15 — Main Rotor Hub Fitting Assemblies - Inspection — 13/88

CANCELLED.

Background: The manufacturer has advised that the inspections of SB 212-77-1 are no longer required, following fitment of shot peened fittings (SB 212-78-3) and MOCA cured TT straps (SB 212-78-4).