AD/BELL 212/52 Main Driveshaft and Tail Rotor Drive Over-Temperature Indicators 10/94

Applicability: All model Bell 212 helicopters S/N 30501 through 30999, 31101 through 31311, 32101 through 32142 and 35001 through 35066.

Requirement: Action in accordance with Bell Helicopter Alert Service Bulletin 212-93-89 Rev A.

Note: Transport Canada AD CF-94-07 dated 11 April 1994 refers.

Compliance: As specified in the Requirement Document effective from 15 September 1994.

Note: The Pilot in Command may carry out and certify in the maintenance release the Requirement Document Part II Serviceability Check required by this directive.

Background: Bell Helicopter has advised that the self adhesive temperature indicators are a more reliable means of over temperature indication than that provided by the zinc chromate primer stripe.