AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BELL 407/13.

Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

AD/BELL 407/13 Oil Cooler Driveshaft Bearings Check 10/2002

Applicability: CANCELLED.

Background: The requirement to inspect the oil cooler bearings was introduced as a result of premature failure of the bearings. Similar problems have also been found in the tail rotor system bearings. As a result, the requirements of this Directive have been included in AD/BELL 407/21.

James Coyne
Delegate of the Civil Aviation Safety Authority

23 August 2002

The above AD is notified in the *Commonwealth of Australia Gazette* on 11 September 2002.