AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive (AD) AD/BELL 407/4.

Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

AD/BELL 407/4 Gearbox Barrier Tape Replacement 5/2002

Requirement: CANCELLED.

Background: This Directive required the tail rotor gearbox barrier tape to be replaced with sealant and a procedure to re torque the attachment nuts after a set period. A new procedure has been developed which is contained within AD/BELL/407/18 to address this problem.

Eugene Paul Holzapfel
Delegate of the Civil Aviation Safety Authority

3 April 2002

The above AD is notified in the *Commonwealth of Australia Gazette* on 24 April 2002.