AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BELL 407/10.

Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

AD/BELL 407/10 — Oil Cooler Blower Assembly - Bearing Change — 10/2002

Applicability: CANCELLED.

Background: Heat generated by engine exhaust has lead to deterioration of the bearings within the oil cooler assembly. This Directive required the replacement of the bearings. The replacement bearings have been found to exhibit similar problems. Similar problems have also been found in the tail rotor system bearings. As a result the requirements of this Directive have been included in AD/BELL 407/21.

James Coyne
Delegate of the Civil Aviation Safety Authority

23 August 2002

The above AD is notified in the *Commonwealth of Australia Gazette* on 11 September 2002.