AD/CESSNA 650/3 — Elevator Torque Tube Inboard Attach Fittings — 3/93 DM

Applicability: Model 650 S/n -0001 to -0219 and 7001 to -7013 inclusive.

Requirement: Inspect the inboard elevator torque tube fittings visually for cracking, and in accordance with Cessna Alert Service Letter SLA650-27-30.

Note: FAA AD 92-27-08 refers.

Compliance: Within 25 hours time in service after 25 January 1993.

Background: There has been a report of cracking of the elevator inboard attach fitting and this Directive is issued to preclude potential loss of elevator control.