AD/DH 104/36 Engine Mounting Frame Front Engine Support Spigots - Inspection 5/81

Applicability: All models equipped with front engine support spigot P/N 4EM.681.

Document: British Aerospace TNS Dove (104) No. 244 Issue 2.

Compliance: Before 15 September 1981.

Background: A case has been reported to the manufacturer where the front engine support spigot, on an engine mounting frame, was found fractured.