AD/DH 104/17 Amdt 2 — Aileron Lever - 4WA315 - Inspection and Modification — 1/70

Applicability: All models not incorporating Mod. 967.

Document: Hawker Siddeley TNS CT(104) No. 151 Issue 4.

Compliance: Inspect at intervals not exceeding 50 hours time in service until modified. Modify before 1 June 1970.