## AD/ECUREUIL/4 — Main Rotor Shaft Star Drive Adapter - Inspection — 8/79

Applicability: All models fitted with main rotor shaft assembly P/N 350A.37.0003.

Document: AS 350 SB 65.01.

Compliance: Within 25 hours time in service after 5 July 1979, and thereafter in accordance with paragraph D(2) of the requirement document.

Background: It is possible to install the rotating star drive adapter incorrectly on the rotor shaft.