AD/ELECT/49 Bendix Magneto Distributor Block 8/95

CANCELLED.

Background: Teledyne Continental Ignition Systems advise that the requirements detailed in Bendix Engine Products Division Service Bulletin No 629 have been incorporated in the applicable magneto service support manuals.