AD/ELECT/36 Slick Magneto Impulse Coupling - Inspection 2/98

CANCELLED.

Background: This AD previously mandated use of the manufacturers' Service Bulletins which have now been incorporated into the magneto manufacturer’s Service Manual.