

Beechcraft 33 and 35-33 (Debonair/Bonanza) Series Aeroplanes

AD/BEECH 33/13

Flap Bracket

8/72

- Applicability: All models which have achieved 1000 or more hours time in service.
- Requirement: Inspect flap actuator bracket and adjacent structure on RH and LH flaps for cracks or signs of distress.
- Compliance: Within 100 hours time in service after 31 August 1972 and thereafter at intervals not exceeding 300 hours time in service.