

Beechcraft 33 and 35-33 (Debonair/Bonanza) Series Aeroplanes

AD/BEECH 33/14
Amdt 1

Wing Front Spar

2/99

Requirement: CANCELLED.

Background: Beechcraft Service Instruction 0514-035 Rev II has been superseded by Service Bulletin 2538 Rev I with reduced model applicability. Corrosion inspection of the upper and lower wing spar caps is called up in the aircraft's maintenance program - therefore separate AD action is no longer considered necessary.