

Beechcraft 95 (Travelair) Series Aeroplanes

---

**AD/BEECH 95/13**  
**Amdt 1**

**Wing Front Spar**

**2/99**

Requirement: CANCELLED.

Background: Beechcraft Service Instruction 0514-035 Rev II has been superseded by Service Bulletin 2538 Rev I with reduced model applicability. Corrosion inspection of the upper and lower wing spar caps is called up in the aircraft's maintenance program - therefore separate AD action is no longer considered necessary.