

Eurocopter BO 105 Series Helicopters

AD/BO 105/8

Tail Boom Skin

3/87

Applicability: All models.

Requirement: Action in accordance with MBB BO 105 Alert Bulletin No 15 Revision 1.

Compliance: As detailed in the Requirement Document.

Background: Cracked tail boom skins have been found in service. LBA Directive 76-317/2 MBB refers.