

Eurocopter BO 105 Series Helicopters

AD/BO 105/3

Tail Rotor Gearbox Attachment

**7/86
DM**

Applicability: All model BO 105 up to and including S/No 780.

Requirement: Action in accordance with MBB Alert Bulletin No. 28.

Compliance: Within 100 hours time in service after 20 June 1986 but no later than 31 July 1986.

Background: Inspection of bolts supplied to the manufacturer has revealed flaws necessitating the replacement of the existing bolts.