

DHC-6 (Twin Otter) Series Aeroplanes

AD/DHC-6/37

**Side Seat Rail Attachment
Rivets - Inspection and Modification**

12/73

Applicability: All models with S/Nos. 136 to 350, 353, 356, 360 to 366 and 368.

Document: De Havilland of Canada SB No. 6/302.

Compliance:

1. For aeroplanes with side facing seats: Within 200 hours time in service after 1 January 1974 or before 1 April 1974 whichever occurs first.
2. For aeroplanes with forward or aft facing seats: Within 1200 hours time in service after 1 January 1974 or before 1 January 1975 whichever occurs first.