

DHC-6 (Twin Otter) Series Aeroplanes

AD/DHC-6/58

Wing Struts Internal Beam Corrosion

9/85

Applicability: All models.

Requirement: Action in accordance with De Havilland Aircraft of Canada Service Bulletin No. 6/474.

Compliance: As per “Requirement” Document.

Background: The manufacturer reports two struts on the same aircraft displaying exfoliation corrosion in the strut beam flanges enclosed by the strut skins.