

This Directive is issued to remove from service and inspect suspect HP turbine discs.