Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/59 Amdt 1 — Flap System - Flap Control Bracket - Inspection and Modification — 12/79

Applicability: All 685, 690 and 690A with S/Nos. referenced in Rockwell SB No. 157A.

Document: Rockwell SB No. 157A.

Compliance: Unless already accomplished, within 100 hours time in service after 31 Dec 1979.