AD/FSM/15 Amdt 2 — Marvel Schebler (Facet Aerospace Products Co.) Carburettors - Throttle Arm Screw - Retorque and Locking — 3/93

CANCELLED.

Background: The requirements of this Directive were originally issued in 1972. Since that time there have been two amendments to reflect revisions to FAA AD 72-06-05. The FAA Directive has a once only compliance requirement of; "Within 30 days of the effective date of this Directive". With a current effective date of 3 July 1986, the requirements of the FAA Directive have been adequately expressed.