## AD/LEARJET 35/2 Spoiler Centre Hinge Brackets - Inspection 4/76

Applicability: All Models: 35 with S/Nos. 35-001 to 35-019;

36 with S/Nos. 36-001 to 36-008.

Document: Gates Learjet SB 35/36-27-2.

Compliance: Before exceeding 300 hours total time in service, or before 30 May 1976 whichever occurs first.