AD/LEARJET 35/18 Horizontal Stabiliser Hinge Pin Bushing Installation - Inspection 12/81

Applicability: All models 35 & 36 with S/Nos. referenced in Gates Learjet Service Bulletin No. 35/36-27-13 or with S/Nos. referenced in subsequent issues of that Service Bulletin.

Document: Gates Learjet SB 35/36-27-13.

Compliance: Within 100 hours time in service after 31 December, 1981.

Background: The horizontal stabiliser hinge pin bushings may move out of their mating fittings during normal service.