AD/PA-20/6 Sensenich M76AM-2 Propellers - Replacement Model M75DM 6/89

CANCELLED

Background: Refer to CAO 107 AD/PFP/15 for restriction on fitment of Sensenich M76AM-2 propeller to Lycoming O-290-D2 engine.