AD/SM-205/17A Aileron and Flap Control Cables - Inspection and Modification 3/74

Applicability: All models.

Document: 1. SIAI Marchetti SB 205B31B; or

2. RAI AD No. 73-176/S205-27, S205-6 Revision 2.

Compliance: Within 50 hours time in service after 29 March 1974 and thereafter at intervals not exceeding 50 hours time in service until modified.