AD/BAe 146/5 MLG Shock Absorber - Lower Attachment Pin 13/87

CANCELLED.

Background: Inspection no longer relevant to SB 32-A61 refers.