COMMONWEALTH OF AUSTRALIA
CIVIL AVIATION SAFETY AUTHORITY

AIRWORTHINESS DIRECTIVE

On the commencement date specified below, and for the reasons set out in the background section, this airworthiness directive (**AD**) is repealed by CASA ADCX 019/16.

British Aerospace BAe 146 Series Aeroplanes

AD/BAe 146/123 Lift Spoiler Actuator Corrosion 22/2016

Requirement: CANCELLED.

This AD is cancelled on 24 October 2016.

Background: The requirements of this AD have been superseded by EASA AD 2006-0139R1 issued on 10 October 2016 with an effective date of 24 October 2016.