AD/BEA 121/7 Elevator Torque Tubes 2/92 Amdt 1

Applicability: All models.

Requirement: Action in accordance with mandatory British Aerospace SB B121/28 Revision 1.

Compliance: As specified in the Requirement Document.

Background: A severely corroded torque tube assembly has been found on an aircraft at a major inspection. SB has been revised and made mandatory by UK CAA.