AD/BEA 121/26 Rudder Control Tube Bolt 10/88 DM

Applicability: All models.

Requirement: Action in accordance with British Aerospace Alert SB B121/94.

Compliance: Prior to further flight after 27 July 1988 and thereafter at each removal/replacement of the subject bolt.

Background: Certain combinations of rudder and elevator control settings have resulted in this bolt fouling the elevator control tube. This may restrict or jam control movement.