AD/BEA 121/18 Rudder Control Lever 10/77

Applicability: All models B121 with Rudder Control Lever P/N BE 45.10193.

Requirement: Action in accordance with Scottish Aviation SB No. B121/72.

Compliance: Within 100 hours time in service after 31 October 1977.