AD/BEA 121/5 Amdt 1 — Rudder Control Lever Assembly P/N BE 45.10193 — 5/71

Applicability: All models.

Requirement: Action in accordance with Beagle SB B121/25.

Compliance:

1. For aircraft not already inspected in accordance with AD/BEA 121/5, and, for those having more than 40 hours time in service since last inspected in accordance with AD/BEA 121/5 - within 10 hours time in service after 13 May 1971; and;

2. For aircraft having less than 40 hours time in service since last inspected in accordance with AD/BEA 121/5 - within 50 hours time in service from last inspection, and

3. Thereafter at intervals not exceeding 50 hours time in service.