AD/BEECH 36/18 Landing Gear Shock Strut Position 1/74 Amdt 1

Applicability: All model A36 with S/Nos. E-425 to E-475 except E-431.

Requirement: Action in accordance with Beechcraft SI No. 612-200.

Compliance: Within 100 hours time in service after 31 January 1974 unless already accomplished.