# AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BEECH 36/8.

## Beechcraft 36 (Bonanza) Series Aeroplanes

## AD/BEECH 36/8 Engine Mount Bolt Nuts 6/2008

Requirement: CANCELLED.

This AD is cancelled on 5 June 2008.

Background: This unique Australian AD, issued in 1970, required a one-off inspection to determine that non-ferrous nuts had not been inadvertently installed in place of steel nuts on engine mount bolts in accordance with Beechcraft Service Instruction (SI) 0396-241. The inspection was to be accomplished within 25 hours TIS after 21 August 1970.

As all affected aircraft will have been inspected, and if necessary modified, long ago, this AD is no longer required.

David Villiers
Delegate of the Civil Aviation Safety Authority

21 April 2008