AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BEECH 36/28.

Beechcraft 36 (Bonanza) Series Aeroplanes

AD/BEECH 36/28 Elevator Control Push Rods 6/2008

Requirement: CANCELLED.

This AD is cancelled on 5 June 2008.

Background: This unique Australian AD, issued in 1980, required a one-off inspection with possible need of anti-corrosion treatment of elevator push rods in accordance with Beechcraft Service Instruction (SI) 1019, within 100 hours TIS after 31 May 1980.

As all affected aircraft will have been inspected, and if necessary modified, long ago, this AD is no longer required.

David Villiers
Delegate of the Civil Aviation Safety Authority

21 April 2008