Beechcraft 36 (Bonanza) Series Aeroplanes

AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BEECH 36/20.

AD/BEECH 36/20 Wing Installation 11/2000

Requirement: CANCELLED.

Background: This AD was issued in 1973 and required a once-off inspection of certain serial number aircraft to check the wing bolts for fitment of incorrect washers. During a review of airframe ADs for other Beech models, it was determined that this requirement could be cancelled because with the passage of time all affected aircraft have by now been inspected, and the fact that none of the affected Beech 36 models remain on the Australian Register.

David Alan Villiers
Delegate of the Civil Aviation Safety Authority

13 September 2000

The above AD is notified in the *Commonwealth of Australia Gazette* on 4 October 2000.