AD/BELL 212/10 Main Beam Cap - Inspection and Repair 12/91

CANCELLED.

Background: The inspection requirements of this AD have been incorporated into the Bell 212 Maintenance Manual. Repair procedures are contained in Bell TB 212-76-12.