AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BELL 212/38.

Bell Helicopter Textron 212 Series Helicopters

AD/BELL 212/38 — Engine Fuel Valve Electrical Connectors P/NO MS3456W14S-5S — 4/2009

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD, issued in 1988, required a one off inspection of engine fuel valve electrical connectors in accordance with Bell Alert SB No 212-87-47 to detect faulty connectors. The AD compliance was by 1 March 1988. As all aircraft would have been inspected by now, the AD is no longer required.

James Coyne
Delegate of the Civil Aviation Safety Authority

16 February 2009