AD/CA25/3 Air Filter Box Rear Mounting Bracket 1/96

Applicability: CA25 Aircraft.

Requirement:

1. Visually inspect the rivets securing the air filter box rear mounting bracket. If the rivets are loose, broken or missing, replace with MS20470AD4-4 solid rivets.

2. Remove the air filter box from the aircraft and replace the pop rivets securing the rear mounting bracket with MS20470AD4-4 or MS20470AD5-4 solid rivets.

Note: Skyfox Aviation Service Bulletin 9 Issue 2 refers.

Compliance: For Requirement 1, before further flight after 4 January 1996.

For Requirement 2, at the next inspection for issue of a Maintenance Release or within 100 hours time in service, whichever occurs first.

Background: The pop rivets originally fitted could work loose and be ingested into the engine. This AD requires fitment of solid rivets.