AD/CA25/5 Throttle Control Grub Screw 6/96

Applicability: Models CA25 and CA25N to Serial No. 032.

Requirement: Action in accordance with Skyfox Aviation SB No. 12 dated 18 March 1996.

Compliance: Part A of SB No 12 - Prior to further flight after 31 May 1996.

Part B of SB No 12 - Within 100 hours time in service after 23 May 1996.

Background: This Directive is issued to prevent possible loss of positive engine control.