AD/CF34/1 Amdt 6 — Life Limits - Engine Rotating Parts — 12/93

CANCELLED.

Background: The service Life-Limit cycles for rotating parts previously identified within Service Bulletin 72-2 (and mandated by this Directive, AD/CF34/1) have been relocated to GE SEI-5800, 5-11-00, TIME LIMITS.

Compliance with that document is already a mandatory requirement for operating the engine as a certificated engine.

The CF34 Turbofan Service Bulletin 72-2 Cancellation Notice dated 16 March 1993 refers.